## UNITED STATES DEPARTMENT OF COMMERCE Patent and Trademark Office

ASSISTANT SECRETARY OF COMMERCE AND COMMISSIONER OF PATENTS AND TRADEMARKS P.O. Box 1450

Alexandria, VA 22313-1450

August 31, 2009

GKN Driveline/TTG c/o Kristin L. Murphy 39533 Woodward Avenue, suite 140 Bloomfield Hills MI 48304

Patent No. : 7,3

: 7,396,285 B2

Inventor(s)

: Thomas Weckerling

Issued

: July 8, 2008

For

COUNTER TRACK JOINT WITH

TRACK TURNING POINT

Doc. No. 66967-0041

To Whom It May Concern:

The Certificate of Correction issued on <u>September 1, 2009</u>, issued in error, in that error(s) was made in identifying the patent number and/or keying text/corrections, i.e.:

Applicant submitted corrections on 1050 in claim and line number format. The cofc was issued in that format. The applicant notated that the error is in Claim 5, Column 13, but the correction should be properly labeled under --Column 13, Claim 5, line 3--. The applicant notated that the error is in Claim 6, Column 13, but the correction should be properly labeled under --Column 13, Claim 6, line 11--. The applicant notated that the error is in Claim 17, Column 14, but the correction should be properly labeled under --Column 14, Claim 17, line 19--. Attorney submitted the 1050 form in improper format. A new certificate of correction will be issued listing the proper format Column and line number.

Therefore, a certificate of correction will be issued to correct (supersede) the Certificate of Correction containing error(s), made during preparation of the Certificate of Correction, as noted above.

No further response is required, from applicants (attorney). However, errors discovered by attorney, other than as noted and described above, should be noted on *a copy* of the Certificate of Correction that was issued in error, accompanied by a signed transmittal letter and submitted directed to this Branch.

Antonio Johnson (703) 756-1584 For Mary F. Diggs, Supervisor Decisions & Certificates of Correction Branch (703) 756-1580